

See discussions, stats, and author profiles for this publication at: <https://www.researchgate.net/publication/279711585>

Performance of a 60-year-old concrete pier with stainless steel reinforcement

Article in Materials performance · October 2002

CITATIONS

44

6 authors, including:



Oladis De Rincon

University of Zulia

138 PUBLICATIONS 888 CITATIONS

[SEE PROFILE](#)

READS

688



Andres Antonio Torres-Acosta

Instituto Tecnológico de Estudios Superiores, Queretaro

97 PUBLICATIONS 782 CITATIONS

[SEE PROFILE](#)



M. Martinez-Madrid

Instituto Mexicano del Transporte

57 PUBLICATIONS 257 CITATIONS

[SEE PROFILE](#)



Asger Knudsen

17 PUBLICATIONS 110 CITATIONS

[SEE PROFILE](#)

Some of the authors of this publication are also working on these related projects:



[Evaluation of nopal mucilage in concrete: durability testing.](#) [View project](#)



[Estudio de escorias de Ni en hormigón para mejorar su durabilidad](#) [View project](#)

Performance of a 60-Year-Old Concrete Pier with Stainless Steel Reinforcement

PEDRO CASTRO-BORGES, *Centro de Investigación y Estudios Avanzados del IPN Unidad Mérida, Depto. de Física Aplicada*

OLADIS TROCONIS DE RINCÓN, *FNACE, Universidad de Zulia, Centro de Estudios de Corrosión*

ERIC I. MORENO, *Universidad Autónoma de Yucatán, Facultad de Ingeniería*

ANDRÉS ANTONIO TORRES-ACOSTA AND MIGUEL MARTÍNEZ-MADRID, *Instituto Mexicano del Transporte, Secretaría de Comunicaciones y Transportes*

ASGER KNUDSEN, *RAMBØLL-Bridge Maintenance and Concrete Technology*

A 60-year-old concrete pier, constructed with stainless steel reinforcing bars (rebar) and exposed to a tropical marine environment, has shown good performance during its service life. This article describes the tests carried out on the pier during this investigation. The tests included visual inspection, chloride content determination, and concrete resistivity as well as electrochemical measurements to the rebar. The authors also discuss durability issues on the pier, based on the results obtained.

The good condition of a concrete pier in the Port of Progreso de Castro in Yucatán, Mexico (Figure 1) has aroused international interest. The pier was built from 1937 to 1941 by a Danish contractor,¹ who presented the winning design to the Mexican government based on the use of 9-m free span concrete arches. The pier dimensions, obtained from a recent survey performed by the Mexican Secretariat of Communications and Transportation (SCT), appear in Figure 2.


The pier (1,752 m long and 9.5 m wide) consists of 146 hinged arches 12-m center-to-center span and 1.6-m high (Figure 2). Each arch is supported at the ends by reinforced concrete girders, each resting on two massive concrete piles. One of the reasons why this design was selected was to eliminate conventional carbon steel reinforcing bars (rebar) by using massive concrete in the substructure. The Mexican authorities wanted to build this pier having low or no corrosion risk, thus avoiding the severe corrosion problems that had developed in several other marine structures in Mexico. This innovative project utilized type 304 stainless steel (SS) (UNS S30400) for girder reinforcement and, in the long term, for corrosion protection. To do so, 220 tons (199,584 kg) of 30-mm-diameter SS, nondeformed bars were used.¹

The pier shows no visible sign of deterioration after 60 years of service,



FIGURE 1
General view of the Progreso pier.

FIGURE 2



Longitudinal section of the pier.

even though the structure has received no maintenance during this period of time, according to port authorities.²

Using modern techniques (mechanical, physical, and electrochemical), several actions have been taken to verify the actual state of the pier to outline maintenance actions to extend the pier's service life. A full-pier examination, based on the preliminary inspection discussed in this article, is scheduled in the near future. This article presents the results of the preliminary inspection as well as the current actions taken as a result of the inspection. This preliminary investigation included a visual inspection of the pier substructure and an assessment of chloride penetration and electrochemical parameters on only one girder reinforced with SS rebar.

Experimental Procedure

Initially, a complete visual inspection was performed along the 2-km pier and the wharf substructure, followed by a more detailed inspection. The following tests were performed in order to obtain quantitative information on this pier:

- Concrete: carbonation front, electrical resistivity, and chloride profile.
- Reinforcement: electrochemical potential (E_{corr}) and apparent corrosion rate (I_{corr}).

The girder located at the shoreline was selected to perform these tests. Figure 3 shows the location of the core extractions and electrochemical measurements.

Concrete cores, 50 mm in diameter, were obtained from each girder's edge surfaces to test for carbonation depth, chloride content, and concrete porosity and density. In addition, an SS bar sample was analyzed to determine the chemical composition. Some cores were extracted at specific locations near areas where the reinforcement was exposed from a previous inspection. This allowed investigators to verify the position and condition of the

SS reinforcement. The total chloride content was estimated from a dry powder concrete sample using an acid-digestion extraction, followed by a potentiometric titration determination according to well-established methods.³

E_{corr} and I_{corr} values were obtained using a commercially available linear polarization instrument with a guarding electrical confinement array. The sensor was placed on top of the longitudinal SS bars of girder #9, with one rebar facing the sea (north face), and the other facing inland (south face) (Figure 3). In the same manner, resistivity measurements were performed using a four-point Wenner array.

Results and Discussion

VISUAL INSPECTION

Of the 146 arches, ~100 were visually inspected and few cracks were observed. Only six arches presented 3-


mm-wide cracks. A total of 15 arches presented narrow cracks, with crack widths in the range of 0.1 to 1.0 mm. As the arches were made of massive, nonreinforced concrete, there is no risk of metal corrosion. A detailed inspection of the damage in the near future was recommended, however.

No corrosion stains or corrosion-induced cracks were observed in the entire pier and wharf substructure. Only a few damaged girders at the wharf showed exposed SS bars—probably caused by ship impact—besides the exposed steel observed in girder #9.

MATERIALS CHARACTERIZATION

The SS was identified as AISI 304 grade (0.08% C, 18% Cr, 8.6% Ni) by energy dispersion analysis (using a scanning electron microscope) in agreement with a previous investiga-

FIGURE 3



Location of the core extractions and electrochemical measurements on the pier.

tion.⁴ The microstructure was identified as austenitic with ASTM grain size No. 8.

The fine and coarse aggregate, observed from the extracted cores, consisted of crushed limestone with a coarse aggregate nominal maximum size of 25 mm. The concrete total porosity was estimated using the ASTM C642⁵ standard test method. The values ranged from 19 to 24%. The estimated concrete density was 2.2 gm/cm³. Based on a petrographic analysis from a previous investigation,⁴ the water/cement (w/c) ratio was estimated to be in the range of 0.50 to 0.70, with a mean value in the range of 0.55 to 0.60.

The carbonation depth, measured on three of the extracted concrete

cores, ranged from 0 to 1.5 mm. These low values, considering the low-quality concrete, may stem from the concrete's high level of chloride contamination.

CONCRETE RESISTIVITY

Resistivity measurements showed values ranging from 0.6 to 2.5 kΩ-cm in the entire girder surface (Table 1). This defines a highly aggressive medium for most metals. Confirming those values in other girders would indicate a high risk of corrosion because the lowest value is similar to the lowest resistivity observed in marine concrete.⁶ These low-resistivity values were expected because the reported w/c ratio used in this structure is characteristic of a low-quality concrete.

E_{corr} AND I_{corr} MEASUREMENTS

The E_{corr} and I_{corr} values reported in Table 2 are usually associated with depassivation and corrosion of SS.^{7,8} The agreement in the results observed from both tests is a good indication that the tests were not affected by transformations of Fe²⁺ to Fe³⁺.⁹ Usually, the linear polarization resistance test cannot be used to evaluate corrosion rates if a proximity exists between E_{corr} and the redox potential of another reaction (the results incorporate the effect of all redox processes). In this case, because of the negative corrosion potential measured (~−350 mV vs copper/copper sulfate [Cu/CuSO₄] electrode [CSE]), the contribution of the Fe²⁺/Fe³⁺ current density is not possible (~+455 mV vs CSE).⁹

According to a previous report regarding this pier,¹⁰ SS bars were directly exposed in the west face of girder No. 9 because of insufficient concrete cover (<1 cm). Because these portions of reinforcement belong to the bended part of end hooks, stress corrosion cracking (SCC) has affected these areas (Figure 4). The SCC was also evaluated in this investigation. At this time, it is unclear whether SCC was an initial or subsequent event: either the chloride ion caused SCC in the embedded steel and then the loss of the concrete cover or the steel was first ex-

TABLE 1
RESISTIVITY
MEASUREMENTS
IN NO. 9 GIRDER

Face	Resistivity kΩ-cm		
	Point East → West		
	P ₁	P ₂	P ₃
North	1.63	0.63	0.63
South	2.51	1.57	2.2

Face	Point North → South		
	Point North → South		
	P ₁	P ₂	P ₃
East	2.2	1.63	1.88
West	0.94	0.63	1.26

TABLE 2

CORROSION POTENTIALS AND CORROSION RATES IN NO. 9 GIRDER

Corrosion Potentials (mV vs CSE) and Corrosion Rates ($\mu\text{A}/\text{cm}^2$)

		Point East → West										
Face		P ₁	P ₂	P ₃	P ₄	P ₅	P ₆	P ₇	P ₈	P ₉	P ₁₀	P ₁₁
North	E _{corr}	-278	-276	-276	-272	-263	-280	-283	-283	-283	-290	-291
	I _{corr}	0.067										0.015
South	E _{corr}	-479	-473	-475	-471	-466	-463	-479	-463	-463	-466	-451
	I _{corr}	0.22										0.618
		P ₁₂	P ₁₃	P ₁₄	P ₁₅	P ₁₆	P ₁₇	P ₁₈	P ₁₉	P ₂₀	P ₂₁	P ₂₂
East	E _{corr}	-278	-285	-283	-285	-285	-285	-287	-281	-268	-309	-346
	I _{corr}										0.030	
West	E _{corr}	-452	-452	-447	-446	-443	-444	-445	-440	-439	-441	-441
	I _{corr}										0.1	
Point North → South												
Face		P ₁	P ₂	P ₃	P ₄							
East	E _{corr}	-536	-553	-340	-350							
	I _{corr}	0.519		0.306								
West	E _{corr}	-475	-475	-358	-363							
	I _{corr}	0.868		0.351								

posed (because of the low concrete cover) and then SCC occurred. By comparing the results from reference (4) with the visual inspection reported here, it is clear that after 3 years the corrosion of the reinforcement has not significantly worsened.

Very severe localized corrosion was observed on the top of an SS rebar located in the east face, however. This rebar was exposed after the previous investigation (December 1998), and it is located in a vertical position with 3 cm of concrete cover. Corrosion was not observed on the bottom of the rebar, where the seawater from the marine breeze tends to accumulate, thereby creating an ideal place for the initiation of corrosion.

In order to verify the validity of the E_{corr} and I_{corr} measurements, the researchers obtained concrete cores from the area above the exposed SS bar. These cores helped to confirm the position of the SS bar inside the girder and the surface condition of the unexposed metal. Figure 3 shows the locations of the extracted cores. The insert

shows a small part of the embedded SS bar surface condition exposed after concrete core drilling. A few rusty spots were observed and identified as pitting.

CHLORIDE CONTENT

The tropical marine environment of the northern Yucatan Peninsula has been characterized in terms of its atmospheric aggressiveness as a grade 5 on the International Organization for Standardization (ISO) scale.¹¹⁻¹² This designation represents the most aggressive marine environment on this scale. As a result of the aggressiveness and the high porosity of the concrete, high chloride concentrations at the rebar level were expected.

Figure 5 shows the chloride profile concentrations obtained from two different cores, one extracted from the west face and the other from the south face. The chloride concentrations at the rebar depth obtained in this investigation are in agreement with those obtained in the previous survey.¹⁰ The maximum chloride concentration ob-

tained was somewhat above the maximum soluble chloride concentration in solutions. This maximum value should not be considered impossible to achieve if one considers that the concrete cores were obtained above the waterline and thus were not saturated. The chloride extraction method was used to obtain total chlorides, and the dry concrete mass was not corrected by water-filled porosity that will decrease the concentration by ~10%.

The chloride threshold for AISI 304 was estimated to be between 0.7 and 1 wt% of concrete.¹³⁻¹⁴ According to the chloride profiles obtained for the evaluated girder (Figure 5), the chloride content measured at the rebar depth (~1.2 wt% of dry concrete) is above the chloride threshold reported for this type of rebar. However, a higher chloride threshold for AISI 316 and AISI 316 clad bars has been reported elsewhere.^{7,13}


The previous results regarding E_{corr}, I_{corr}, and chloride content at the bar depth confirm that the SS rebar at girder No. 9 is in the process of active corrosion. This situation demands a fur-

FIGURE 4



Girder No. 9, where most of the tests were performed. SCC occurred on rebar exposed at this girder.

FIGURE 5



Chloride concentration profiles in girder No. 9.

ther analysis to corroborate—by means of a more extensive and systematic study—if other girders beyond the shoreline are also experiencing corrosion degradation.¹⁵

STRATEGIES FOR FUTURE DETAILED INSPECTION

As a result of the preliminary inspections already performed on this pier, a detailed inspection program has been

presented to the SCT government authorities. The program includes the selection of six bents to perform tests on the piles, girders, and arches. Future testing will include the determination of chloride profiles, carbonation front, concrete resistivity, I_{corr} , E_{corr} , total and effective concrete porosity, and petrographic analysis.

The results of these tests would allow the researchers to determine, with a higher degree of confidence, the chemical and physical characteristics of the pier's materials. Consequently, it would enable them to predict the residual service life of the pier and to outline an effective maintenance program.

Conclusions

A preliminary inspection of the Progreso pier in Yucatán, Mexico, provided enough quantitative information to suspect that the SS bars from the girders are exposed to a high chloride concentration that is possibly causing their depassivation.

A detailed inspection program has been recommended to Mexican government authorities in order to verify this hypothesis.

Acknowledgments

The authors acknowledge partial support from Consejo Nacional de Ciencia y Tecnología (CONACYT) (Mexico City, Mexico), Fondo Nacional de Ciencia, Tecnología Innovación (FONACIT) (Caracas, Venezuela), Centro de Investigación y de Estudios Avanzados (CINVESTAV) del IPN Unidad Mérida (Mérida, Mexico), Instituto Mexicano del Transporte, and FIUADY for this investigation. The authors are indebted to C. Andrade and A. Sagüés for helpful discussions and to M. Balancán and G. Diaz for performing the tests. The opinions and findings are those of the authors and not necessarily those of the supporting organizations.

References

1. A. Christensen, "Pier at Progreso," 50 Years of Civil Engineering (Christiani & Nielsen, 1954).
2. A. Arroyo, M. Ganzo, Port Authorities, personal communication, October 2001.
3. P. Castro, L. Maldonado, "Initial Efforts to Evaluate the Corrosion Problems in the Infrastructure of the Mexican Southeast Coastal Zones," in Innovative Ideas for Controlling the Decaying Infrastructure, ed., V. Chaker (Houston, TX: NACE, 1996), p. 119.
4. Arminox, RAMBØLL, "Pier in Progreso, México, Inspection Report-Evaluation of the Stainless Steel Reinforcement" 3 (1999).
5. ASTM C642, "Standard Test Method for Density, Absorption, and Voids in Hardened Concrete" (West Conshohocken, PA: ASTM, 1997).
6. O. Troconis, et al., "Manual for Inspection, Evaluation and Diagnosis of Corrosion in Reinforced Concrete Structures" (in Spanish), DURAR Report (Maracaibo, Venezuela: CyTED, 1997): p. 208.
7. F. Cui, A. Sagüés, "Corrosion Behavior of Stainless Steel Clad Bar," CORROSION/2001, paper no. 645 (Houston, TX: NACE, 2001).
8. American Society of Metals International, Metals Handbook Vol. 13 Corrosion, 9th edition (Metals Park, OH: ASM International, 1987): p. 557.
9. C. Alonso, C. Andrade, M. Izquierdo, X.R. Novoa, M.C. Pérez, "Effect of Protective Oxide Scales in the Macrogalvanic Behaviour of Concrete Reinforcements," Corrosion Science 40 (1998): p. 1,379.
10. A. Knudsen, T. Skovsgaard, "The Optimal Use of Stainless Steel Reinforcement in Concrete Structures," in Third International Conference on Concrete under Severe Environments, Vol. 1, eds., N. Banthia, K. Sakai, O. Gjørv (Vancouver, Canada: The University of British Columbia, 2001): p. 1,360.
11. L. Maldonado, L. Véleva, "Corrosivity Category Maps of a Humid Tropical Atmosphere: The Yucatán Peninsula," Materials and Corrosion 50 (1999): p. 261.
12. P. Castro, "The Atmospheric Corrosion Performance of Reinforced Concrete in the Peninsula of Yucatán, México. A Review," Corrosion Reviews 17 (1999): p. 333.
13. Arminox technical brochure, "ARMINOX-A strong connection," ARMINOX, DK-8800, Viborg, Denmark (1998).
14. D. McDonald, M. Sherman, D. Pfeifer, P. Virmani, "Stainless Steel Reinforcing as Corrosion Protection," Concrete International 17, 5 (1995): p. 65.
15. K. Tuutti, "Corrosion of Steel in Concrete," CBI Research Report 4:82 (Stockholm, Sweden: Swedish Cement and Concrete Research Institute, 1982).
16. P. Castro, "The Chloride Threshold for Corrosion Onset of Reinforced Concrete in Two Tropical Marine Micro-climates of Yucatán, Mexico," in Third International Conference on Concrete Under Severe Environments, Vol. I, N. Banthia, K. Sakai, O. Gjørv, eds. (Vancouver, Canada: The University of British Columbia, 2001), p. 151.
- PEDRO CASTRO BORGES** is a Researcher at Cinvestav del IPN Unidad Mérida, Km 6 Antigua Carretera a Progreso, CP 97310, Mérida, Yucatán, Mexico. He specializes in concrete durability, including inspection, evaluation, diagnosis, service life, and repairs. He has a Ph.D. from the National University of Mexico and a Postdoctorate from the Institute of Construction Sciences Eduardo Torroja in Spain. He has been a NACE member since 1992.
- OLADIS TROCONIS DE RINCÓN, FNACE**, is Director of the Corrosion Study Center, The University of Zulia, Av. Goajira, Faculty of Engineering, Apdo. 10482, Maracaibo, Zulia, Venezuela. She has 26 years of experience in the corrosion field. Her research interests include corrosion and corrosion control in reinforced concrete structures, metallic coatings, and atmospheric corrosion. She is the International Coordinator of the Iberoamerican project DURACon/CyTED Program. A 27-year member of NACE, she was named a NACE Fellow in 2000.
- ANDRES A. TORRES-ACOSTA** is Materials Chief Engineer at the Instituto Mexicano del Transporte (IMT), Km 12+000 Carretera Queretaro-Galindo, Sanfandila, Queretaro, 76700, Mexico. He is Chairman of the Mexican Section of the CYTED-Duracon Iberoamerican-Network Project. He works in the areas of construction materials and durability of concrete structures. He has a Ph.D. in civil engineering from the University of South Florida and was the first-place recipient of the Mars Fontana Award given at the CORROSION/98 Student Poster Session. He is a 5-year member of NACE.
- ERIC IVAN MORENO** is a Professor at Universidad Autónoma de Yucatán, Av. Industrias No Contaminantes s/n x Arillo Periférico Norte, Mérida, Yucatán, Mexico. He has 10 years of research experience in the area of electrochemical monitoring and corrosion of reinforcing steel in concrete. He has an M.S. and Ph.D. from the University of South Florida and has been a NACE member since 1992.
- ASGER KNUDSEN** is Project Director at RAMBØLL, Bredevej 2, 2830 Virum, Denmark. He has extensive project management experience in Denmark and abroad in inspection and rehabilitation of concrete and steel structures. The assignments have involved inspection, testing, reporting, and preparing rehabilitation projects and specifications.
- MIGUEL MARTÍNEZ MADRID** is a Researcher at UNAM, Centro de Física Aplicada y Tecnología Avanzada, Campus Juriquilla, Juriquilla, Santiago de Queretaro, Qro 76230, Mexico. He develops technologies that can be applied in Mexico's metal and oil industry. He is a 2-year member of NACE. **MP**

This article is based on CORROSION/2002 paper no. 207, presented in Denver, Colorado.